## 1. SCOPE

By performing a **maintenance program**, you ensure your electrical rotating machine operates as required, within safe conditions, both for the machine and the operators.

A maintenance program includes the scheduling of preventive and predictive maintenance tasks, for which the rules may vary depending on: the type and size of machine, the operating conditions, the duration of operation and rest periods, etc. The main difficulty is not to determine its content but the interval between each maintenance.

Evaluating the condition of brushes, brush-holders, commutators and slip rings, however, is a challenging task, and should be performed only by an experienced engineer or technician. Our brochure "How to maintain carbon-brushes, brush-holders, commutators and slip rings" gives main lines to put you on the way to such a diagnostic.

The present document only gives a list of essential inspections and maintenance operations for optimal brush operation, listed in a chronological order:

- inspection during operation and until machine stops,
- controls at standstill, including visual checks and measurements to be carried out,
- maintenance (machining, grinding, brushes replacement, etc...) and measurements to perform,
- inspection during operation.

In practical, it is easier to work with a checklist, which could then be attached to the machine follow-up file. It constitutes the level 1 of maintenance.

It is obvious that other maintenance operations not mentioned in this document may be required (e.g. insulation of windings, maintenance of bearings). In general, they are specified in the maintenance guide of the machine manufacturer.

## 2. CHECK-LIST OF MAINTENANCE

The checklist in following pages is intended to be as general as possible. It should therefore be adapted to the type of the machine.

Legend:

Y = Yes N = No N/A = Not applicable



VERY IMPORTANT:

All work carried out on rotating electrical machines is subject to a decommissioning procedure, even for visual inspection.

When the machine has just stopped, some parts may be very hot (brush shunts, brushholders, sliding surface, etc.). It is recommended to wait until the temperature has decreased.

Note: Visual inspection is the primary means of inspection, so it may be useful to take pictures that can be included in a report, to document the observations.

MERSEN PROPERTY



# **PREVENTIVE MAINTENANCE CHECK-LIST**

Date:	Completed by:	

## General information on the machine

Plant		Machine reference	
OEM		Part number	
Date and co	omments of previous maintenance:		

## Inspection before and during slow down

Check:	shaft	bearings	brushes	other parts	if yes, precise
Vibration level:	$\Box Y \Box N$				
Noise:	$\Box Y \Box N$				
Spark level (TDS-14)	Arm 1		□ 3 □ 4		
and per track, if applicable	Arm 2		□ 3 □ 4		
	Arm 3	□ 1 □ 2	□ 3 □ 4		
Any other remark:					

## Inspection when stopped (see note page 1)

	Commutator / rings			Track / ring 1	
Just after stop				Track / ring 2	
			Track / ring 3		
Running time:	Real:		Since last stop:		

#### **Brushes:**

## Wear assessment and brush aspect: Length (mm) Wear rate (mm/1000h) Wear Arm / Brush Aspect Average per phase number (mm) previous current Per brush group

(add lines when necessary)

**MERSEN PROPERTY** 





TDS-08

## **Brush-holders**

Visual inspection:		Integrity of a	all parts?	Any sign of	vibration?	Any pollutio	n?
-		□ Y	□ N	□ Y	□ N	□ Y	□ N
Comments	(if any):						
Measuremer	nts after brusł	n removal (add	d lines when n	ecessary)		·	
Arm / pole	Brush-	Brush box dimensions (mm) – see TDS-04		Distance to the	Pressure –	see TDS-11	Position to
number	noider number	4	a	surface	🗆 kg	□ g/cm²	radial axis
		l	a	(mm)	□ cN	□ kPa	
Visual inspection after brushes back into							
Brush is correctly guided?						□ 0	□ N
Correct position of pressure system?						□ 0	□ N

## Commutator / slip ring

Visual inspection:	Integrity of the rotor? Any sign of		vibration?	Any pollution?		
	□ Y	□ N	□ Y	□ N	□ Y	□ N
Film	Film aspect description (see TDS-13)		Conform? <sup>1</sup>	Need for maintenance?		
Track 1			□ Y □ N	□ Y □ N		
Track 2				□ Y □ N	□ Y □ N	
Track 3				□ Y □ N		





**TDS-08** 

Measurements Concentric		ity / Runout	Roughness Ra (see TDS-02)		Number of peaks / cm <i>Rpc</i> (see <i>TDS-02</i> )	
	Value	Conform? <sup>1</sup>	Value	Conform? <sup>1</sup>	Value	Conform? <sup>1</sup>
Track 1		$\Box Y \Box N$		□ Y □ N		
Track 2		$\Box Y \Box N$		□ Y □ N		
Track 3		$\Box Y \Box N$		□ Y □ N		
Specific						
Commutators: interbar aspect, chamfers (see TDS-03)						
Slip rings: helical grooves chamfers (see TDS-03)	s aspect,					
Other <sup>2</sup>						

(add lines when necessary)

<sup>1</sup> see Mersen documents, in particular Technical Guide on Maintenance and TDS.

<sup>2</sup> Other measurements may be performed to control the state of the machine, maybe at a higher maintenance step level: windings insulation resistance, neutral line (*see TDS-06*). We recommend you to refer to the O&M's manual.

## **Maintenance work**

Activity	Done?	Measurements / Comments	Conformity?
Cleaning			
Commutator / ring machining		Out-of-round (µm):	
Commutator / ring grinding	□ O □ N	Roughness <i>Ra</i> (µm) : <i>Rpc</i> (pics/cm) :	
Brush-holders replacement / repair	□ O □ N		□ O □ N
Brush replacement			
Other (precise)			

MERSEN PROPERTY

Expertise, our source of energy



If the machine is intended to be stored (not used after the maintenance operation), specific precautions shall be taken, in particular:

- protect the commutators or rings from damage and oil leaks (strips of cardboard, clean rag, covering, etc.),

- remove all brushes or insert a strip of insulating material between the brush and the sliding surface (see TDS-22).

Cited documents (available from Mersen website): - Mersen Technical Guides: Brushes for motors and generators. How to maintain carbon-brushes, brush-holders, commutators and slip rings

Mersen PTT Technical data sheets (TDS):
TDS-02: Surface condition of commutators and rings: Roughness
TDS-03: Bar edge chamfering – Machining of helical grooves
TDS-04: Dimensions of carbon brushes and brush-holders
TDS-06: Setting the neutral
TDS-09: Circumferential brush stagger
TDS-11: Pressure on carbon brushes
TDS-13: Aspect of commutator / slip-ring skins
TDS-14: Brush sparking
TDS-22: Ghost marking on slip rings
TDS-23: Silicones



The specifications or data contained in present catalogue are only given for information and do not create any undertakings whatsoever. Any copy, reproduction or translation, either partially or fully, of these information is subject to the Mersen's prior written consent. In addition, due to the continuing improvement of techniques and change of applicable standards, Mersen is entitled to modify at any time the characteristics and specifications of its products as described in present catalogue.

#### Contact: info.ptt@mersen.com



Expertise, our source of energy